

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Figure 1




Figure 2




Figure 3




Figure 4




Figure 5




Figure 6




Figure 7




Figure 8




Figure 9




Figure 10

Figure 10 is a cross-sectional view of a multi-layered structure 210. The structure includes a top layer 36, a middle layer 30 with a textured region 32, and a bottom layer 122. A central assembly 140 is shown, consisting of a base 144, a middle section 130 with a striped pattern, and a top section 142. A circular feature 38 is positioned above the central assembly. Various other layers and interfaces are labeled with numbers 34, 132, 136, 141, 134, 138, 184, 224, 226, 186, and 220.

Figure 11




FIGURE 12




FIGURE 13




FIGURE 14




FIGURE 15




FIGURE 16




FIGURE 17




FIGURE 18




FIGURE 19




FIGURE 20




FIGURE 21




FIGURE 22




FIGURE 23




FIGURE 24.




FIGURE 25




Figure 26:

